




## Filing Receipt

**Received - 2022-04-27 02:53:57 PM**  
**Control Number - 50595**  
**ItemNumber - 219**



## Public Utility Commission of Texas

### Employee Training Report Required by 16 Texas Admin. Code § 25.97(d)

**PROJECT NO.** 50595

**AFFECTED ENTITY:** RAYBURN COUNTRY ELECTRIC  
COOPERATIVE INC.

#### General Information

Pursuant to 16 Texas Admin. Code § 25.97(d)(2), not later than the 30th day after the date an affected entity finalizes a material change to a document or training program, the affected entity must submit an updated report. The first report must be submitted not later than May 1, 2020.

#### Instructions

Answer all questions, fill-in all blanks, and have the report notarized in the Affidavit.

#### Affidavit

A representative of the affected entity must swear to and affirm the truthfulness, correctness, and completeness of the information provided by attaching a signed and notarized copy of the Affidavit provided with this form.

#### Filing Instructions

Submit four copies (an original and three copies) of the completed form and signed and notarized Affidavit to:

Central Records Filing Clerk  
Public Utility Commission of Texas  
1701 N. Congress Avenue  
P.O. Box 13326  
Austin, Texas 78711-3326  
Telephone: (512) 936-7180

**Affected Entity:** RAYBURN COUNTRY ELECTRIC  
COOPERATIVE INC.

**PROJECT NO.** 50595

**1. Provide a summary description of hazard recognition training documents you provide your employees related to overhead transmission and distribution facilities.**

Rayburn Country Electric Cooperative has a hazard recognition training plan as required by OSHA. The American Public Power Association (APPA) Safety Manual is the standard resource provided to each employee. The APPA manual covers a wide variety of topics for electric facilities, including employee responsibility for safety and reporting of hazardous conditions. We have regularly scheduled safety meetings where accidents and near misses are discussed and countermeasures are initiated to help prevent future incidents. "Rayburn Safety Shares" that identify concerns, mitigation efforts and lessons learned are circulated companywide to ensure transparency and to promote a safety conscious culture.

**Affected Entity:** RAYBURN COUNTRY ELECTRIC  
COOPERATIVE INC.

**PROJECT NO.** 50595

**2. Provide a summary description of training programs you provide your employees related to the National Electrical Safety Code for construction of electric transmission and distribution lines.**

Rayburn Country Electric Cooperative has licensed Professional Engineers provide training to applicable employees on required clearances between energized conductors and various possible situations as formulated by the National Electrical Safety Code. The use of examples and illustrations reinforces the concepts, and the open dialogue forum allows for questions and answers to be exchanged in an informative manner.

Affected Entity: RAYBURN COUNTRY ELECTRIC  
COOPERATIVE INC.

50595  
PROJECT NO.

### AFFIDAVIT

I swear or affirm that I have personal knowledge of the facts stated in this report or am relying on people with personal knowledge, that I am competent to testify to them, and that I have the authority to submit this report on behalf of the affected entity. I further swear or affirm that all statements made in this report are true, correct, and complete.



Signature

Stephen Geiger

Printed Name


COO

Job Title

RAYBURN COUNTRY ELECTRIC COOPERATIVE INC.

Name of Affected Entity

Sworn and subscribed before me this 27<sup>th</sup> day of April, 2022.  
Month Year



Notary Public in and For the State of Texas

My commission expires on 12/12/2023

